# This Page Is Inserted by IFW Operations and is not a part of the Official Record

### **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


### IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Problem Image Mailbox.







## STAGE ASSEMBLY INCLUDING A REACTION ASSEMBLY HAVING A CONNECTOR ASSEMBLY Mike Binnard





# STAGE ASSEMBLY INCLUDING A REACTION ASSEMBLY HAVING A CONNECTOR ASSEMBLY Mike Binnard PA0568-US / 11269.65











Fig. 3B





# STAGE ASSEMBLY INCLUDING A REACTION ASSEMBLY HAVING A CONNECTOR ASSEMBLY Mike Binnard PA0568-US / 11269.65

















Fig. 5A




Fig. 5B